# SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

## Port Authority® Easy Care V-Neck Sweater. SW2850

**Product photo**



Blending professionalism with supreme comfort, this beautiful tri-blend sweater is an exceptional addition to any work wardrobe.

- 56/29/15 cotton/nylon/acrylic
- Fully-fashioned seams
- Machine washable
- 2x2 rib knit V-neck, cuffs and hem

**CARE INSTRUCTIONS**

Turn Garment Inside Out. Machine Wash Cold With Like Colors. Gentle Cycle. Only Non-Chlorine Bleach When Needed. Reshape And Lay Flat To Dry. Warm Iron If Needed.

**Sketches**



front



back

## PRODUCT MEASUREMENTS

| | XS | S | M | L | XL | 2XL | 3XL | 4XL |
|---|---|---|---|---|---|---|---|---|
| Body Length at Back | 25 1/2 | 26 1/2 | 27 1/2 | 28 1/2 | 29 1/2 | 30 1/2 | 31 | 31 1/2 |
| Chest | 18 1/2 | 20 | 21 1/2 | 23 | 24 1/2 | 26 | 28 | 20 |
| Sleeve Length from Center Back | 33 5/8 | 34 1/4 | 34 7/8 | 35 1/2 | 36 1/8 | 36 3/4 | 37 1/2 | 38 1/4 |

**Body Length at Back:** Measured from high point shoulder to finished hem at back.


**Chest:** Measured across the chest one inch below armhole when laid flat.

**Sleeve Length from Center Back:** Measure from Center Back neck to shoulder point to sleeve hem.

## SIZE CHARTS

| | XS | S | M | L | XL | 2XL | 3XL | 4XL |
|---|---|---|---|---|---|---|---|---|
| Chest | 32-34 | 35-37 | 38-40 | 41-43 | 44-46 | 47-49 | 50-53 | 54-57 |

## HOW TO MEASURE




**CHEST**

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

## COLORS



Charcoal Heather
PMS 7540C



Deep Black
PMS BLACK C



Medium Heather Grey
PMS 425C



River Blue Navy
PMS 533C